



MODEL:- SUPERLUX TK HEAD



1 PROBLEMS WITH CONTACTS AFTER BEING INSTALLED INCORRECTLY.



2 RE-ALIGN & RE-SEAT CONTACTS WITH LONG NOSE PLIERS.



3 HOW TO INSTALL THE TK-HEADS CORRECTLY. ENSURE THAT THE REBATE ON THE TK-HEAD HOUSING IS ALIGNED WITH THE ALIGNMENT RIB ON THE TK-TRACK. THEN ROTATE THE HOUSING IN THE CORRECT DIRECTION AND ENGAGE THE LOCKING MECHANISM.

